

Geyer Road Tree Data - October 2021

Tree Num	Common Name	Condition	DBH	Tree Comments
1	redbud	Fair	10	Prune 6" limb
3	stump	Dead	20	20' tall stump dead Honeysuckle along road
4	pine eastern white	Critical	16	Severe lean toward road. Soil lift.
5	pine eastern white	Critical	22	Severe lean to south. Soil lift. Leaning on adjacent tree.
6	pine eastern white	Fair	12	lean to south. Adjacent leaner pushing it.
7	mulberry	Fair	22	Multiple Stems
8	oak post	Fair	24	Lean away from road. To west. Basal damage with woundwood. Basal decay likely.
9	maple silver	Fair	34	Evidence of past pruning of large limbs pruned towards road. Crown Dieback
10	hackberry	Good	16	Approx 10' from xst curb
11	oak shingle	Fair	20	
12	elm slippery	Good	20	
13	elm slippery	Fair	28	
14	redbud	Fair	8	Approx 7' from curb
15	elm slippery	Fair	26	Approx 12' from curb. Lg limbs pruned in past.
16	ash green	Critical	8	Severe dieback and lean.
17	hackberry	Poor	20	Approx 12' from curb. Severe dieback. Mechanical Damage
18	pine eastern white	Fair		Several white pine outside of proposed excavation. Some w lean.
19	pine eastern white	Fair		Several white pine outside of proposed excavation. Some w lean.
20	maple silver	Fair	16	Crown Dieback
21	maple silver	Fair	12	Crown Dieback
22	maple silver	Fair	18	Crown Dieback
23	magnolia saucer	Good		Approx 12' from curb
24	spruce norway	Good		Prune low limbs
25	spruce norway	Good		Prune low limbs
26	redbud	Fair	10	Downslope. Fill needed will require removal
27	hackberry	Fair		4-5 hackberry at drainage. May need to be removed for storm water work.
28	Juniper spp	Fair	14	Approx 12' from curb